



Overshoot detector

For MetalStar 2

Additional sensor for detecting early sheets.

The overshoot detector monitors the gap between the previous and the following sheet by means of a photo sensor on the feeder table. If this gap is not detected, this is recognised by the sensor as an early sheet, and the press stops with a fast stop (emergency stop).

After the early sheet has been removed and the error message reset, the press can be restarted and the print job continued.

This upgrade is suitable for all MetalStar 2 type presses.

The advantages	Your benefit
<ul style="list-style-type: none"> Reliable detection of early sheets 	<ul style="list-style-type: none"> Increased production reliability
<ul style="list-style-type: none"> Prevention of crashes, as the printing press is stopped in time 	<ul style="list-style-type: none"> Prevention of unnecessary downtimes
<ul style="list-style-type: none"> Prevention of major damage in the region of the feed drum 	<ul style="list-style-type: none"> Prevention of unnecessary repairs

Depending on the technical configuration of your equipment we can offer a comprehensive consultation service. We will be pleased to supply you with a quotation tailored to your specific needs. Please feel free to contact us.

Tel. +49-711-6 99 71-300 · Fax +49-711-6 99 71-185 · spare-parts@kba-metalprint.de

KBA-MetalPrint GmbH

Wernerstr. 119-129 · 70435 Stuttgart, Germany
 Phone +49 711 699 71-0 · Fax +49 711 699 71-670
info@kba-metalprint.de · www.kba-metalprint.com